

Montážní(y) návod 85.

Assembly instructions 85.

Montageanleitung 85.

GP 1200 2	H-T 5 3 S, 2x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
GP 1500 2	H-T 5 2 S, 3x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
PP 1200 2	H-T 5 3 S, 2x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
PP 1500 2	H-T 5 2 S, 3x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
CP 1200 2	H-T 5 3 S, 2x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
CP 1500 2	H-T 5 2 S, 3x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
FP 1200 2	H-T 5 3 S, 2x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
FP 1500 2	H-T 5 2 S, 3x H-SPP, H-CN T 730, H-CN S 250, H-CN K 400
KS 1200 C	H-T 3 E S, H-CN T 525, H-CN S 450, H-CN K 500
JS 2400 C	2x H-T 5 3 S, 2x H-SPP, 3x H-CN T 730, 2x H-CN S 250, H-CN S 450, 2x H-CN K 400, H-CN K 500
JS 3000 C	2x H-T 5 2 S, 2x H-SPP, 3x H-CN T 730, 2x H-CN S 450, H-CN S 600, 2x H-CN K 500, H-CN K 600
JS 2600 C	H-TI 260 S, 4x H-CN T 730, 2x H-CN SO 700, 2x H-CN V 760, H-CN V 2010
JS 2600 SC	H-TS 260 S, 4x H-CN T 730, 2x H-CN SO 700, 2x H-CN V 760, H-CN V 2010
MS 900 550	H-TK 90 S, H-CN T 450, H-CN SK 600, H-CN K 600
MS 900 755	H-TK 90 S, H-CN T 650, H-CN SK 600, H-CN K 600
MS 900 790	H-TK 90 S, H-CN T 670, H-CN SK 600, H-CN K 600
CNK 525 450	H-CN T 525, H-CN S 450, H-CN K 500
CNK 670 450	H-CN T 670, H-CN S 450, H-CN K 500
CNK 730 250	H-CN T 730, H-CN S 250, H-CN K 400
CNK 730 450	H-CN T 730, H-CN S 450, H-CN K 500
CNK 730 600	H-CN T 730, H-CN S 600, H-CN K 600
CNO 730 700	2x H-CN T 730, H-CN SO 700, H-CN V 760, H-CN K 600

H-CN SK 600	4 ks		H-CN T 525	5 ks		
	4 ks			H-CN T 670	1 ks	
	1 ks			H-CN T 730	1 ks	
				4 ks		
				4 ks		
			H-CN T 450	1 ks		
			H-CN T 650	1 ks		
				4 ks		
				4 ks		



